

PI-05302	Product info
1	Decontamination tools
Rev. 2	Page 1 / 2

.9501

Decontamination tools

For the decontamination of surfaces there are some usefull products with can clean smooth surfaces and floors in zones with particulate radioactive or toxic contamination.

Alcatum impregnated towels

The towels for smooth surfaces are used for cleaning, decontamination and degreasing. One side with scratching effect that does not strip the supports. The towel does not leave any marks after drying. It is lint-free. PMUC no 02-0065.

Application video of Alcatum impregnated towels

Alcatum towels for floor

Decontamination towels for cleaning and decontaminating floors, designed for trapezoid brooms. Do not leave marks after drying. Lint-free. PMUC no 02-0065.

Application video of Alcatum towels for floor



GNS 054

Self-drying neutral gel to neutralize and remove dust, remove labile contamination and degrease the supports.




Aerofix blue

Spray of a fixative film in aerosol to fixe the contamination on textiles and flexible plastic materials (i.e ventilated suits). The spray forms a blue color film resistant to high temperatures and UV.



Available products:



Other products on request.



PI-05302 Rev. 2 Page 2 / 2

Surface decontamination tool

Wall and floor scraper: Impact spatula with 800 mm long handle, 80 mm wide sharp cut hardened blade



Item-no.	Tool
116343	Impact spatula L = 800 mm

Other products on request.